autoistorija.lt

Volkswagen Arteon

VIN kodas

WVWZZZ3HZNE509626

Sugeneruota: **2026-10-20**

Informacija

Pagrindiniai automobilio duomenys ir atliktų patikrinimų santrauka

Markė, modelis
Volkswagen Arteon

Rida

Nerasta neatitikimų ridos istorijoje

Vagystės

Įrašų nerasta

Nuotraukos

Automobilio istorinės nuotraukos nerastos



Dirbtinio intelekto įžvalgos:

Pagal mūsų turimus duomenis, šio automobilio ridos istorija atrodo nuosekli ir tvarkinga. Aptarnavimų įrašai Vokietijoje rodo tolygų kilometražo augimą be jokių įtartinų pokyčių ar neatitikimų. Kaip ir visada, prieš įsigyjant bet kokį naudotą automobilį, rekomenduojame jo būklę papildomai pasitikrinti pas profesionalus – tai standartinė gera praktika.

Automobilio techninė informacija

(Originalo kalba)

Production date	2022-06-03	Fuel type	Petrol
Model	Arteon SB ELE P 115 TSID6F	Displacement	1.40
Series	Arteon	Drive type	FWD
Type code	3H93YY	Steering side	Left
Engine code	DGEB 4-cylinder SI engine 1.4 l TSI hybrid 115 kW	Color	Kings Red Metallic/Kings Red Metallic
Power	115	Interior	Titanium Black/Titanium Black/Titanium Black
		Transmission	automatic
		Transmission code	UYJ

Automobilio komplektacija

(Originalo kalba)

PE0A	No special edition

PGP1	Vehicles with special upgrade measures
P1SA	Without additional front underbody guard
PQQ0	Without add. lights (interior lighting)
P1E1	Activated carbon canister
PKK3	Refrigerant R1234yf
PKS0	Without head-up display
P3FA	Without roof insert (standard roof)
P0Y1	Standard climatic zones
P4D0	Without seat ventilation/massage seat
P5C0	Without special body measures
P7ZS	Vehicle class differentiation -3H0-
P8Z5	Not hot country
P8FC	Installation of SLI battery in rear, without second battery
PQH1	Voice control
PEF1	ECO function
PFC0	Without customized installation
PF0A	No special purpose vehicle, standard equipment
PQA0	Without child seat
PIG0	Standard curb weight range
P0YE	Weight range 5 installation control only, no requirement forecast
P0FA	Standard manufacturing sequence
P5K7	Transport protection film (minimum protection) with additional transport protection measures
P2WA	Without additional tires
P7G0	Without preparation for VTS (vehicle tracking system)
P1Z0	Initial standard fuel filling
P3LF	Door and side trim panel in foam film, insert in leatherette
P5D1	Carrier frequency 433.92 MHz-434.42 Mhz
P7QA	Without CD/DVD for navigation
PL47	Suspension range 47 installation control only, no requirement forecast
P6A0	Without fire extinguisher
P8Y1	Two-tone horn
P3CX	Net partition
PAV1	Driving on the right
P1S3	Tool kit
P1Y0	Without differential lock
PNY0	Standard battery/alternator capacity
PFB0	Standard paint coating
P2A0	Without delivery equipment
P7U0	Standard engine starter
P9D0	Without preparation for two-way radio installation

P1JL	Rear shock absorption
P0P1	Rear side exhaust tailpipe
P1Q2	Mass damper for steering wheel, 36 Hz
PA60	Category 0
P4BI	Emission standard EU6 AP
P0K3	Hybrid propulsion system PHEV
P0M5	Fuel tank
PC22	Operating permit, alteration
PK8R	Sportsback
P0RF	With electronic steering column lock
PPW9	Parking heater and ventilation with radio remote control and timer
P0B5	Wheelbase
PFM5	Hybrid variant
PMV3	4-cylinder SI engine 1.4 l TSI hybrid 115 kW
PTH8	4-cylinder SI engine 1.4 l
P4ZB	Chrome moldings on the side windows
P8RM	8 speakers
PB0A	Part set without country-specific prescriptive standard
PEM1	Driver alert system
PL0L	Left-hand drive
PQG1	LongLife Service Regime
P6Q2	Gearshift knob in leather
P7K1	Tire pressure monitoring system
P0NB	Elimination of nameplate for engine designation on luggage compartment lid
P0TD	Carpet mats in front and rear
P1PE	Wheel locks with extended theft protection
P1X0	Front-wheel drive
P1ZK	Disc brakes in front
P2EI	Disc brakes in rear
P31K	License plate carrier in front and rear (ECE)
P3H0	Non-folding front passenger seat backrest
P3QT	3-point seat belts in front with height adjustment and seat belt pretensioners
P3T2	3 head restraints in rear
P3ZU	3-point seat belts with seat belt pretensioners for the outer rear seats
P4A4	Heated front and outer rear seats
P4GF	Laminated safety glass windshield, heat- and sound-insulating
P4L6	Auto-dimming interior rearview mirror
P4X3	Curtain airbag system for front and rear passengers incl. side airbags in front
P5RQ	Right exterior mirror, convex
P5SL	Aspherical exterior mirror on driver side
P5XJ	Illuminated vanity mirrors in sun visors

P6K4	Autonomous Emergency Braking Front Assist (for Adaptive Cruise Control ACC up to 210 km/h)
P6NA	Headliner
P7L6	Start-stop system with regenerative braking
P7W4	Proactive passenger protection system in combination with Front Assist and Side Assist
P7X5	Park Assist with Park Distance Control
P7Y1	Lane change system Side Assist and Rear Traffic Alert
P8AR	Radio
P8N6	Rain sensor
P8Q5	Dynamic headlight range control with dynamic cornering light
P8T8	Adaptive Cruise Control ACC stop & go incl. speed limiter
P8X0	Without headlamp washer system
P9P9	Warning signal and warning lamp for front and rear seat belts not fastened
P9S0	Multi-color Digital Cockpit "Pro" selection of different info profiles possible
P9T1	Automatically-heated washer nozzles in front
P9WJ	App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto
PKH7	Air Care Climatronic 3 zone automatic climate control with enhanced air filterand controls in the rear
PQ4H	Premium comfort seats in front
PQK1	Multifunction camera
PQV3	Digital radio reception DAB+
PUH2	Electromechanical parking brake with Auto Hold function
P1N7	Progressive steering
P3D3	Decorative inserts "Piano Black" for center console
P3GA	Luggage compartment floor
P3KB	Unsplit rear bench seat, asymmetric split folding backrest, with center armrest and load-through hatch
P3U1	Luggage compartment cover
P3W4	Acoustics package "Standard"
P3Y0	Without roll-up sunshade
P4B4	Lower side trims in chrome
P4UN	Driver and front passenger airbag with front passenger airbag deactivation, including knee airbag on driver side
P4V0	Without front passenger seat control
P6SE	Textile luggage compartment trim
P7B6	12-V outlet in center console in rear
P7E0	Without heat accumulator/auxiliary heater
P7M1	Scuff plates w/ stainless steel inserts
P8WM	Cornering light and poor weather light

P9TJ	LED entry/warning lights in front doors
PA8C	Comfort equipment
PQJ3	Chrome elements on door pulls, on the rotary light switch and on the front vents
PUG6	Hill Start Assist
PVC0	Without garage door opener
PVF1	Pedals in brushed stainless steel
PVL4	Pedestrian monitoring and re-active hood
P5ZF	Safety-optimized front head restraints
PKA2	Rear view camera system
PV0A	Tires without specification of tire brand
PU9C	USB-C interface and USB charging socket
P1A5	Fuel system for fuel-injected SI engine
PQI4	Service indicator 15 000 km or 1 year (fix)
PU5A	Instrument cluster with electronic speedometer, odometer and trip odometer, tachometer
P6T1	LED light unit in front footwell
P2I0	Adaptive Chassis Control DCC incl. Driving Profile Selection
P9JA	Non-smoker's package: 12-V outlet in front
P6Y8	Electronic restriction of top speed
P8TL	Rear fog light on one side, back-up light on both sides
PJ0B	Battery 520 A (92 Ah)
P9B0	Without integrated toll system
P1G0	Elimination of Tire Mobility Set
P8I2	Lumbar supports in front, power- adjustable on driver side, massage feature on driver side
P5I3	Easy Open & Close - sensor controlled luggage compartment opening and closing with remote unlocking
P8IU	IQ.LIGHT - LED matrix headlamps with LED separate daytime running light and dynamic cornering light
P8S6	Interior lights with switch-off delay and dimmer, 2 LED reading lights in front and 2 in rear
P8VP	3D LED rear combination lamps with dynamic turn signal
P4F2	Keyless locking and starting system Keyless Access with SAFELOCK
P7AL	Anti-theft alarm system with interior monitoring, backup horn, and towing protection
P1EX	Special identification label for EC for M1 passenger vehicles
PER1	Regional code " ECE " for radio
PN0R	Inserts of front seats and outer rear seats in ArtVelours microfleece, inner sides of bolsters in leather "Vienna"
P0SB	Labels in German

P4KF	Privacy glass for rear side windows and rear window
P8G3	Advanced high-beam control Dynamic Light Assist
P1M6	Folding trailer hitch, with electric release
P3PW	Front seats with height adjustment, ergoComfort seat on driver side, with electrical backrest adjustment
P8ZQ	Diversity antenna for FM reception
P6XI	Ext. mirror w/ surround lighting a. fr. passenger ext. mirror lowering funct., folding/heated, auto-dimming on dr. side
PG10	Shock absorption in front
PQR9	Dynamic Road Sign Display
PB01	Type approval country Germany
PX0A	Equipment options subset for Germany
PEL5	Online service, with OCU, with head unit coding, without engine immobilizer interconnection
PNZ4	Emergency call service; no registration required, service is activated upon delivery
PSZ9	Delivery "Autostadt Wolfsburg"
P6E3	Front center armrest with storage compartment, 2 rear vents
PWD5	Anti-theft alarm system
PYOS	Preparation for We Connect and We Connect Plus
P6I6	Comfort drive Travel Assist, lane keeping system Lane Assist and Emergency Assist
P7UG	Navigation system "Discover Pro" incl. Streaming & Internet
PRCB	Navigation system "Discover Pro" incl. Streaming & Internet
P2PE	Leather-wrapped multi-function sports steering wheel, with touch control and shifting paddles
PPEL	Easy Open & Close package with SAFELOCK
P9M9	Parking heater and ventilation with radio remote control and timer
P1T9	First aid kit, warning triangle and safety vest
PEV3	Mains charging cable for household outlet
P0IC	Dual-clutch transmission DSG DQ400
P20C	Electric motor (hybrid electric vehicle), total system output 160 kW, unit 0EC.B / 0EK.A
P9Z3	230-V outlet in center console in rear
P1AE	Electronic Stability Control and electromechanical brake booster
P8GZ	Without alternator
PES3	AC vehicle inlet
P0VC	Manual in German (Germany)
P9IP	Mobile phone interface "Comfort" with inductive charging feature
PPF5	Driver assistance package

P2F1	Preparation for mobile key for vehicle access via smartphone
PG1A	6-speed automatic transmission or dual-clutch transmission DSG, note: PR family EDF
PYCR	Environment bonus
PJ83	AirStop® tires 245/45 R18, rolling resistance class A
PGM4	Electronic engine sound
PYTZ	Campaign
PWBA	"Business Premium" package
P3A0	ISOFIX anchorage points for mounting of 2 child seats on rear bench seat, also for i-Size child seats
P9I5	Separate daytime running light with automatic headlight control and automat. Coming and Leaving Home feature
P2JW	Body-colored bumpers
P7TP	Decorative inserts in ornamental wood "Eucalyptus" for dashboard and door trim panels
P45Q	4 alloy wheels "Valdemossa" 8J x 18
PPJF	"Valdemossa" 8J x 18, AirStop® tires 245/45 R18
LC3J/	Kings Red Metallic/Kings Red Metallic

Istorija

Automobilio istorijos įvykiai ir įrašai pateikiami laiko juostoje

Atkreipk dėmesį: Informaciniai tekstai, kurie parašyti kita kalba yra išversti į lietuvių kalbą. Galite pasirinkti žiūrėti originalo kalba.

Žiūrėti originalo kalba

2022

Aptarnavimas

2022-06 | Vokietija

Atlikti darbai:

Perdavimo patikra.

Aptarnavimas

2022-06 | Vokietija

Atlikti darbai:

Patikra prieš pristatant

Aptarnavimas

2023-03 | Vokietija | 16 367 km

Atlikti darbai:

Oil change service.

Aptarnavimas

2024-02 | Vokietija | 34 231 km

Atlikti darbai:

Apžiūra su alyvos keitimu.

Aptarnavimas

2025-03 | Vokietija | 53 112 km

Atlikti darbai:

Oil change service.
Stabdžių skysčio keitimas.
Dulkių ir žiedadulkių filtras.
Dirbtuvės pastaba.

Aptarnavimas

2026-04 | Vokietija | 67 556 km


Atlikti darbai:

Apžiūra su alyvos keitimu.
Pavarų dėžės alyva
Uždegimo žvakė.

Rida

Užfiksuota automobilio rida ir jos pokyčiai laikui bėgant

Autoistorija.lt įžvalga:
Mūsų duomenys gaunami iš įvairių oficialių duomenų šaltinių, tačiau mes vis tiek, rekomenduojame atlikti profesionalią automobilio apžiūrą su specialistais.



Eismo įvykiai / žalos / defektai

Užfiksuoti duomenys apie galimus automobilio apgadinimus ir su jais susijusius įvykius

Puiku! Šioje ataskaitoje neradome jokių oficialių įrašų apie žalas ar eismo įvykius.

Tai dažnai yra geras ženklas, rodantis, kad transporto priemonė galimai nebuvo patekus į avarijas ar rimtesnius incidentus ir buvo naudojama atsakingai.

Vis dėlto svarbu pažymėti, kad ne visi įvykiai visada patenka į oficialias duomenų bazes. Kai kurie incidentai gali būti neužfiksuoti arba neprieinami mūsų informacijos šaltiniuose. Duomenys pateikiami remiantis trečiųjų šalių informacija, tad jų nebuvimas ataskaitoje nereiškia garantijos, kad įvykiai tikrai nevyko.

Todėl, kaip ir su bet kuriuo naudotu automobiliu, rekomenduojame papildomai įsivertinti transporto priemonės būklę, pasikalbėti su pardavėju arba pasikonsultuoti su specialistu.

Gamintojo atšaukimai

Gamintojo paskelbtos saugos ir techninio aptarnavimo kampanijos

3 **Rasta gamyklinių atšaukimų**

Duomenų šaltiniai: 3+

Atkreipk dėmesį: Informaciniai tekstai, kurie parašyti kita kalba yra išversti į lietuvių kalbą. Galite pasirinkti žiūrėti originalo kalba.

Žiūrėti originalo kalba

Viso atšaukimų: 3

Duomenų šaltiniai: 3+

Gamintojo atšaukimas

2024-01 | 13456

Netinkamai sumontuotas karščio izoliacijos kilimėlis tarp stabdžių skysčio bakelio sankabos atvamzdžio ir išmetamųjų dujų apdorojimo sistemos gali lemti sankabos atvamzdžio išsilydymą ir stabdžių skysčio nuotėkį, kuris gali užsidegti.

Taisomieji veiksmai

Patikrinamas tinkamas karščiui atsparaus kilimėlio sumontavimas, prireikus atkuriama tinkama apsauga nuo karščio.

Gamintojo atšaukimas

2022-03 | 11696

Dėl klaidingos atitinkamo saugiklio specifikacijos trumpojo jungimo atveju gali padidėti elektros smūgio ir gaisro pavojus.

Taisomieji veiksmai

Atitinkamose transporto priemonėse virš aukštosios įtampos akumuliatoriaus jungiklių dėžutės bus pritvirtintas papildomas apsauginis izoliacinis kilimėlis.

Gamintojo atšaukimas

2022-03 | 11703

Dėl nepakankamo variklio dekoratyvinio gaubto pritvirtinimo jis gali liestis su karštomis dalimis ir dėl to gali kilti gaisras.

Taisomieji veiksmai

Dekoratyvinis variklio dangtis nuimamas

Vagysčių patikra

Policijos ir kitų duomenų bazių informacija apie tai, ar automobilis nėra paieškomas.

Neradome jokių įrašų, jog transporto priemonė būtų pavogta.

Įrašai apie galimas transporto priemonės vagystes buvo atliekami šių šalių duomenų bazėse:

- Lietuva
- Slovėnija
- Slovakija
- Čekija
- Vengrija
- Italija
- Rumunija
- Vokietija